

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2018

Submitted Date:

08/15/2018

Document Number:

689301743**FIELD INSPECTION FORM**

Loc ID 324139	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																
Operator Information: OGCC Operator Number: <u>10550</u> Name of Operator: <u>MUSTANG RESOURCES LLC</u> Address: <u>1660 LINCOLN STREET SUITE 1450</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80264</u>																				
Contact Information: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Lemon, Deb</td> <td></td> <td>dlemon@mustangresourcesllc.com</td> <td></td> </tr> </tbody> </table>					Contact Name	Phone	Email	Comment	Lemon, Deb		dlemon@mustangresourcesllc.com									
Contact Name	Phone	Email	Comment																	
Lemon, Deb		dlemon@mustangresourcesllc.com																		
Inspected Facilities: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>258987</td> <td>WELL</td> <td>PR</td> <td>12/01/2016</td> <td>GW</td> <td>045-07675</td> <td>SAVAGE 11-35-6-94 W</td> <td>PR</td> </tr> </tbody> </table>					Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	258987	WELL	PR	12/01/2016	GW	045-07675	SAVAGE 11-35-6-94 W	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status													
258987	WELL	PR	12/01/2016	GW	045-07675	SAVAGE 11-35-6-94 W	PR													
General Comment: <u>Routine Field Inspection</u>																				

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	1-888-291-8588	
Corrective Action:		Date:

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 2		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 258987	Type: WELL	API Number: 045-07675	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Well producing			
Corrective Action:				Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301744	Inspection photo 689301744	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4553134