

Inspection Photos

08/14/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 436744

Inspection Doc. Number: 682503718
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 1: Photo taken from the access road, facing north. Photo shows no additional reclamation activities, including but not limited to, removing gravel, compaction alleviation, recontouring/regrading and revegetation activities appear to have been conducted.



Photo 2: Photo taken from the access road, facing north. Photo shows no additional reclamation activities, including but not limited to, removing gravel, compaction alleviation, recontouring/regrading and revegetation activities appear to have been conducted.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 3: Photo taken from the access road. Photo shows gravel remaining.



Photo 4: Photo taken from the where the access road meets the east/west ranch road, facing southwest. Photo shows no additional reclamation activities, including but not limited to, removing gravel, compaction alleviation, recontouring/regrading and revegetation activities appear to have been conducted.