

Inspected Facilities

Facility ID: 436311 Type: WELL API Number: 123-39048 Status: PR Insp. Status: PR

Producing Well

Comment: PR, valves shut at wellhead.

Corrective Action:

Date:

Complaint

Comment: Inspection in response to complaint.

Field Inspector Assigned: Adam Kraich

Complaint Received:

Date: 8/14/2018

Complaint Contacted:

Date: 8/14/2018

Location #: 436310

Inspection Document #: 691300435

Nature of complaint: Air Quality

Field Inspector Actions:

On 8/14/2018; I received a complaint in regard to C-scale vibration, suspected to be coming from the Hawkstone 29-30DD facility, owned and operated by Bayswater.

On 8/14/2018, I performed a complete inspection of the facility (436310). The well was hard shut in at the wellhead. Additionally, the equipment on location was de-energized, including VOC combustors.

I have also inspected a facility west of the complainant's subdivision and found the well hard shut in as well as de-energized equipment.

After speaking with the complainant, of my findings, I have referred him to local government as we have eliminated the source of C-scale from being an oil & gas issue.

No violation of COGCC rules were observed at the time of the inspection.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 691300436 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555301 |