

# *Inspection Photos*

*Loc#425092*

*Operator: Laramie*

*Inspection Number: 692400013*

*Inspection Date: 7/30/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#1:**

Overview of Location from entry to Northwest. Red oval indicates area of close up view in Photo#2.

July 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie NBC Elk Ranch Loc#425092





**Photo#2:**

Close up view of area circled in Photo#1; showing vehicle traffic disturbance & ingress into Location.

July 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie NBC Elk Ranch Loc#425092





Photo#3:  
Overview of Location to Southeast.

July 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie NBC Elk Ranch Loc#425092





Photo#4:

Close up of ground conditions showing little germination of desirable species.

July 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie NBC Elk Ranch Loc#425092





Photo#5:

Areas of Noxious weeds do not appear to have been affected by controls, if applied.

July 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie NBC Elk Ranch Loc#425092





Photo#6:  
Stormwater erosion is commencing in center area of Location.



Photo#7:

July 30, 2018