

# *Inspection Photos*

*Loc#427788*

*Operator: Caerus*

*Inspection Number: 692400016*

*Inspection Date: 7/31/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to North.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Albertson Loc#427788





**Photo#2:**

View from NW corner of site over Pad , showing Russian thistle plants that will become Debris.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Albertson Loc#427788





Photo#3:

Majority of Vegetation within portions of the Interim Reclamation areas, is cheat grass, interspersed with thistle & other annual weeds. Insert is close up of vegetation in this area.

July 31, 2018





Photo#4:  
Noxious weeds on site that appear to have not been affected by controls .



Photo#5:

July 31, 2018