

# *Inspection Photos*

*API#045-06239*

*Operator: Maralex*

*Inspection Number: 692400018*

*Inspection Date: 7/31/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to Southwest.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex API#045-06239





Photo#2:

One area of Panels upon which netting is layered has been damaged, allowing ingress of smaller Wildlife, who even though Pit is dry at this time would not be able to find egress.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex API#045-06239