

Inspection Photos

Loc#335304

Operator: Terra

Inspection Number: 692400028

Inspection Date: 8/14/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to North.

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335304



Photo#2:

Perimeter Wattles are not properly installed.

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335304



Photo#3:
Perimeter Wattles are not properly installed..



Photo#4:

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335304