

# Inspection Photos

Operator: Gunnison Energy

API: 05-051-06073

Date: 7/25/2018



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.**



**Photo 3. View of the eastern portion of the northeastern corner facing southward.**



**Photo 4. View of black plastic netting on northern slope that needs to be removed.**