

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301550**



Location Photo #1

Location Photo #2

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301550**



Location Photo #3



Location Photo #4

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301550**



Location Photo # 5, Oil stained material in battery containment

Location Photo # 6, Oil stained material in battery containment

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301550**



Location Photo #7, Oil stained material in battery containment



Location Photo #8, Oil stained material in battery containment

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301550**



**Location Photo #9, Oil stained material in
battery containment**