

Construction and Stormwater Inspection

August 10, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 455750

Inspection Document #: 682403882

Adams County, CO

SWNW Section 13 T3S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Left Hand /3-65 13-18
Location ID: 455750



Photo 1. Photo taken from the access road, facing South. Operator has disturbed a section of land between the access road and the location. Operator is responsible for all future reclamation throughout any portion of land that was disturbed.

Inspection Photos
Location Name: Left Hand /3-65 13-18
Location ID: 455750



Photo 2. Photo taken from the northeastern perimeter of the location, facing South. Photo illustrates a sediment basin that appears to be in proper functioning condition. Operator has installed a ditch that continues north of the sediment basin. Operator will be responsible for that ditch disturbance (contouring and vegetation standards).

Inspection Photos
Location Name: Left Hand /3-65 13-18
Location ID: 455750



Photo 3. Photo taken from the northeastern perimeter of the location, facing North. Photo illustrates the previously mentioned ditch that continue north of the sediment basin.

Inspection Photos
Location Name: Left Hand /3-65 13-18
Location ID: 455750



Photo 4. Photo taken from the eastern soil stockpile, facing South. Soil stockpiles have been seeded and crimped with filtrex wattles along the base.



Photo 5. Photo taken from the eastern soil stockpile, facing Southwest. Photo illustrates the Operator stabilizing the location.

Inspection Photos
Location Name: Left Hand /3-65 13-18
Location ID: 455750



Photo 6. Photo taken from the eastern soil stockpile, facing West. See comments under Photo 5.