

# Construction and Stormwater Inspection

August 10, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 455198

Inspection Document #: 682403884

Arapahoe County, CO

SWNW Section 26 T4S R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Chico /4-65 26-25  
Location ID: 455198



**Photo 1.** Photo taken from the southwestern location, facing South. Photo illustrates the area that will appear to be used as the sediment basin stormwater area. Operator has installed filtrex wattles along the entire perimeter of the location during initial construction operations.

Inspection Photos  
Location Name: Chico /4-65 26-25  
Location ID: 455198



**Photo 2.** Photo taken from the southwestern perimeter of the location, facing East. See comments under Photo 1.



**Photo 3.** Photo taken from the southwestern perimeter of the location, facing North. Photo illustrates a soil stockpile. Appears the Operator is in-process of salvage soil material.

Inspection Photos  
Location Name: Chico /4-65 26-25  
Location ID: 455198



**Photo 4.** Photo taken from the northern perimeter of the location, facing West. Photo illustrates a portion of the access road to the location.



**Photo 5.** Photo taken from the northern perimeter of the location, facing Southwest. Photo illustrates a water truck that was on location.