

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2018

Submitted Date:

08/20/2018

Document Number:

682403884**FIELD INSPECTION FORM**Loc ID 455198 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COPColoradoReg@conocophillips.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455194	WELL	XX	05/25/2018		005-07365	Chico 4-65 26-25 3AH	CI
455195	WELL	XX	05/25/2018		005-07366	Chico 4-65 26-25 2BH	CI
455196	WELL	XX	05/25/2018		005-07367	Chico 4-65 26-25 2CH	CI
455197	WELL	XX	05/25/2018		005-07368	Chico 4-65 26-25 2DH	CI

General Comment:

This is a Construction and Stormwater Inspection in response to Form 42: Notice of construction- Document #401723794.

Location Construction

Location ID: 455198 CDP: _____

Comment: A disturbance area of 11.60 acres was mapped on 8/10/2018 using a Trimble Juno 3B handheld device; this appears to be in compliance with the approved Form 2A for the permitted disturbance area.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>455194</u>	Type: <u>WELL</u>	API Number: <u>005-07365</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>455195</u>	Type: <u>WELL</u>	API Number: <u>005-07366</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>455196</u>	Type: <u>WELL</u>	API Number: <u>005-07367</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>455197</u>	Type: <u>WELL</u>	API Number: <u>005-07368</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____ In _____

Comment _____

Operator currently in-process of salvaging topsoil. A follow-up inspection will occur at a future date to ensure compliance with Rule 1002.b. standards. Refer to the attached inspection photos for more detail.

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ In Process _____

Comment _____

Appears topsoil is being stored along the eastern location perimeter. A follow-up inspection will occur at a future date to ensure compliance with Rule 1002.c. standards.

Per Rule 1002, all stockpiles shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					

Comment: The BMP (filtrexx wattle) appears sufficient during topsoil salvage and initial pad construction operations. More permanent BMPs should be installed upon the completion of pad construction. A follow-up inspection will occur at a future date to ensure the Operator is in compliance with Rule 1002.f. standards.

BMPs shall be selected based on site-specific conditions, such as slope, soil type, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the construction BMPs until the Location is abandoned and final reclamation is achieved pursuant to Rule 1004.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682403885	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4556843