

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/20/2018

Submitted Date:
08/20/2018

Document Number:
689701730

FIELD INSPECTION FORM

Loc ID 335668 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

23 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282873	WELL	PR	11/27/2006	GW	045-11864	N.PARACHUTE WF 12D K26 596	PR
282874	WELL	PR	11/29/2006	GW	045-11863	N.PARACHUTE WF 11B K26 596	PR
282875	WELL	PR	11/29/2006	GW	045-11862	N.PARACHUTE WF06D K26 596	PR
282878	WELL	PR	11/29/2006	GW	045-11861	N.PARACHUTE WFO5D K26 596	PR
282880	WELL	PR	11/29/2006	GW	045-11860	N.PARACHUTE WF 11D K26 596	PR
282881	WELL	PR	01/26/2006	GW	045-11859	N.PARACHUTE WF 9C-27 K26 59	PR
282882	WELL	PR	06/30/2008	OG	045-11858	N.PARACHUTE WF 16D-27 K25 5	PR
282883	WELL	PR	01/26/2006	GW	045-11857	N.PARACHUTE WF 13B K26 596	PR
292314	WELL	PR	03/15/2009	GW	045-14688	N. PARACHUTE WF02A-35 K26 59	PR
292315	WELL	PR	09/19/2007	GW	045-14687	N. PARACHUTE WF 13D K26 596	PR
292316	WELL	PR	04/01/2009	GW	045-14686	N. PARACHUTE WFO2C-35 K26 59	PR
292317	WELL	PR	03/20/2009	GW	045-14685	N. PARACHUTE WF 14A K26 596	PR
292318	WELL	PR	04/15/2009	GW	045-14684	N. PARACHUTE WF01D-35 K26 59	PR
292319	WELL	PR	03/20/2009	GW	045-14683	N. PARACHUTE WF14C K26 596	PR
292320	WELL	PR	04/15/2009	GW	045-14682	N. PARACHUTE WF08A-35 K26 59	PR
292321	WELL	PR	03/20/2009	GW	045-14681	N. PARACHUTE WFO7A-35 K26 59	PR

General Comment:

Follow up to inspection 689700948
Corrective actions have been completed.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Volume has been added to tank label.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Type: Gas Meter Run	# 16		
Comment:	Sells		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containers at gas runs		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)	120 bbls				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	282873	Type:	WELL	API Number:	045-11864	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282874	Type:	WELL	API Number:	045-11863	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282875	Type:	WELL	API Number:	045-11862	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282878	Type:	WELL	API Number:	045-11861	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282880	Type:	WELL	API Number:	045-11860	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282881	Type:	WELL	API Number:	045-11859	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282882	Type:	WELL	API Number:	045-11858	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282883	Type:	WELL	API Number:	045-11857	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 292314	Type: WELL	API Number: 045-14688	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 292315	Type: WELL	API Number: 045-14687	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 292316	Type: WELL	API Number: 045-14686	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 292317	Type: WELL	API Number: 045-14685	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 292318	Type: WELL	API Number: 045-14684	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 292319	Type: WELL	API Number: 045-14683	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 292320	Type: WELL	API Number: 045-14682	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 292321	Type: WELL	API Number: 045-14681	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Berms	Pass					
Compaction	Pass					
				Covering Materials	Pass	
		Ditches	Pass			
		Compaction	Pass			
		Culverts	Pass			
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701731	Inspection 689701730 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4557028