

Inspection Photos

Location Name: Nickerson - 67N58W /18SWNW

Location #: 326976



Colorado Oil & Gas Conservation Commission
40.57645, -103.91415, 1465.0m, 177°
2018/08/20 03:23:36 PM

Photo #1

Nickerson 4 (API # 05-123-13962) wellhead



Colorado Oil & Gas Conservation Commission
40.57703, -103.91647, 1473.0m, 178°
2018/08/20 03:53:50 PM

Photo #2

Nickerson 4 (API # 05-123-13962) Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Nickerson - 67N58W /18SWNW

Location #: 326976



Photo #3

Nickerson 4 - Battery sign
Phone number is correct.
Answers by voicemail



Photo #4

Nickerson 4 (API # 05-123-13962) Engine
Stained soil around engine base

Inspection Photos

Location Name: Nickerson - 67N58W /18SWNW

Location #: 326976



Photo #5

Nickerson 4 – Engine house

Stained soil outside of engine house



Photo #6

Nickerson 4 - Containers

Placarding is illegible



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Nickerson - 67N58W /18SWNW

Location #: 326976



Photo #7

Nickerson 4 – Pit North side

Gaps under framing / netting



Photo #8

Nickerson 4 – Pit North side

Gaps under framing / netting



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Nickerson - 67N58W /18SWNW

Location #: 326976



Photo #9

Nickerson 4 – Pit South side

Gaps under framing / netting



Photo #10

Nickerson 4 – Separator

No wildlife protection screen

Inspection Photos

Location Name: Nickerson - 67N58W /18SWNW

Location #: 326976




Photo #11

Nickerson 4 – Wellhead

Production valves closed

