

Inspection Photos

Loc#333109

Operator: Terra

Inspection Number: 692400027

Inspection Date: 8/14/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northwest

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP GM 41-4 Loc#333109



Photo#2:

View to North along East Perimeter of Location; No perimeter Controls are evident. Red X shows area of detail in Photo#3.

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP GM 41-4 Loc#333109



Photo#3:

View at Northeast corner of site (red X in Photo#2) where there are No BMPs are installed.

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP GM 41-4 Loc#333109



Photo#4:

No separation, definition between toe of Fill slope & what is identified as Topsoil stockpile in Location drawings.

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP GM 41-4 Loc#333109



Photo#5:
No BMPs installed around Materials Stockpile.

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP GM 41-4 Loc#333109



Photo#6:

View along Cut Slope to West.

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP GM 41-4 Loc#333109



Photo#7:
Views of Ditch & Check dams installed at top of Cut Slope.



Photo#8:

August 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP GM 41-4 Loc#333109