



Photo#1:  
The area of disturbance is approximately 4 Acres.

July 25,, 2018



Photo#2:  
There are several small areas of subsidence & hardened concrete slurry

July 25,, 2018



Photo#3:  
Stained soil piles remain.

July 25,, 2018



Photo#4:  
Material pile remains..

July 25,, 2018



Photo#5:  
Up to 50 Yards of gravel to remove from site. .

July 25,, 2018



Photo#6:  
Drainage discharge from Gas Plant will need to be researched.

July 25,, 2018