

Inspection Photos

Location Name: Boies C-24M Pad

Location ID: #335681

Inspection Date: August 20, 2018



Photo #1 – Well sign.



Photo #2 – Frac tanks staged along north side of location, looking NE.



Inspection Photos

Location Name: Boies C-24M Pad

Location ID: #335681

Inspection Date: August 20, 2018



Photo #3 – Frac tanks staged along south side of location, looking SW.



Photo #4 – Looking east along HDPE surface line, which is located at NE corner of location. Red arrow indicates area where line crosses a drainage that acts as a tributary to Black Sulphur Creek.



Inspection Photos

Location Name: Boies C-24M Pad

Location ID: #335681

Inspection Date: August 20, 2018



Photo #5 – ¼” stainless steel tubing located at west end of tank battery.



Photo #6 – Chemical storage tank at SW corner of tank battery.



Inspection Photos

Location Name: Boies C-24M Pad

Location ID: #335681

Inspection Date: August 20, 2018



Photo #7 – Chemical storage tank located at west end of tank battery.



Photo #8 – Unlabeled ~75 gallon drum and hose located at east end of tank battery.

