

Inspection Photo
Gentry E8
API # 045-14190
Inspection # 689301782



Location Photo #1



Location Photo #2, unmarked anchor

**Inspection Photo
Gentry E8
API # 045-14190
Inspection # 689301782**



Location Photo #3, unmarked anchor



Location Photo #4, E4 well marker

**Inspection Photo
Gentry E8
API # 045-14190
Inspection # 689301782**



Location Photo #5, unmarked flowline near containment.



Location Photo #6, containment maintenance.

**Inspection Photo
Gentry E8
API # 045-14190
Inspection # 689301782**



Location Photo #7, Missing information.



Location Photo #8, missing information.

Inspection Photo
Gentry E8
API # 045-14190
Inspection # 689301782



Location Photo #9, housekeeping, oily rags