

Inspection Photos

Location Name: KAMMERZELL, ED #3-28 Tank Battery

API: 05-123-11889



Colorado Oil & Gas Conservation Commission
40.3255, -104.80784, 1419.0m, 56°
08/22/2018 11:06:50 AM

Berm has eroded on NW side of tanks.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: KAMMERZELL, ED #3-28 Tank Battery

API: 05-123-11889



Berm has eroded on NW side of tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources