

Inspection Photos
Location Name:Kallsen 14-10X
Location ID: 319870



Photo#1 Equipment



Photo#2 ECD

Inspection Photos
Location Name:Kallsen 14-10X
Location ID: 319870



Photo#3 Production Tank and Produced Water pit



Photo#4Wellhead

Inspection Photos
Location Name:Kallsen 14-10X
Location ID: 319870



Wednesday, August 15, 2018 12:57:05
27670 E 160th Ave Brighton CO 80603 United States

Photo#5 **Corrective Action Rubbish**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources