

Inspection Photos
Location Name: Jan#1
Location ID: 319645



Photo#1 Production Tank/Corrective action Berm in disrepair/Labeling for what is in tank needs to be fixed



Photo#2 Corrective action Hole in bottom of production tank

Inspection Photos
Location Name: Jan#1
Location ID: 319645



Photo#3 Corrective Action underneath of tank needs to be filled in.



Photo#4 Pit/Corrective Action many openings around frame and screen. Needs to be fixed to prevent wildlife from entering

Inspection Photos
Location Name: Jan#1
Location ID: 319645



Photo#5 Wellhead



Photo#6 Separator