

Inspection Photos
Well Name: Spaulding Peak 1294 23-33
Location ID: 321999



Photo 1. Wellhead sign.



Photo 2. Wellhead is not connected to any production equipment.

Inspection Photos
Well Name: Spaulding Peak 1294 23-33
Location ID: 321999



Photo 3. Disconnected separators.



Photo 4. Disconnected separators.