

## Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



**Photo #1**

**Federal North Wildhorse 7-28** (API # 05-123-12824)  
wellhead

*From Previous FIR*

Bradenhead not plumbed to surface



**Photo #2**

**Federal North Wildhorse 7-28** - wellhead  
**Bradenhead is plumbed to surface**



## Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



**Photo #3**

**Federal North Wildhorse 7-28** – Pump jack

*From Previous FIR*

*Pump jack gearbox & soil stain*



**Photo #4**

**Federal North Wildhorse 7-28** – Pump jack

**Gearbox cleaned. Soil remediated.**



## Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



**Photo #5**

**Federal North Wildhorse 7-28** – Pump jack

*From Previous FIR*

*Pump jack skid & soil stain*



**Photo #6**

**Federal North Wildhorse 7-28** – Pump jack

**Pump jack skid cleaned. Soil remediated.**



## Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



Colorado Oil & Gas Conservation Commission  
40.63597, -104.09444, 1479.0m, 177°  
2018/07/31 01:04:49 PM

**Photo #7**

**Federal North Wildhorse 7-28 – Engine House**

*From Previous FIR*

*Gas engine area stained soil*



Colorado Oil & Gas Conservation Commission  
40.63602, -104.09441, 1476.0m, 22°  
2018/08/23 11:39:44 AM

**Photo #8**

**Federal North Wildhorse 7-28 – Engine House**

**Gas engine area soil remediated.**



## Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



**Photo #9**

**Federal North Wildhorse 7-28** – Engine exhaust

*From Previous FIR*

*Pump jack gas engine exhaust stained soil*



**Photo #10**

**Federal North Wildhorse 7-28** – Engine exhaust

**Gas engine exhaust area soil remediated.**



## Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



**Photo #11**

**Federal North Wildhorse 7-28 - Battery**

*Photo from previous FIR*



**Photo #12**

**Federal North Wildhorse 7-28 – Pit**


*Photo from previous FIR*



## Inspection Photos

Location Name: Federal North Wildhorse - 68N60W / 28SWNE

Location #: 323292



Colorado Oil & Gas Conservation Commission  
40.63579, -104.09439, 1478.0m, 281°  
2018/07/31 01:27:42 PM

### Photo #13

**Federal North Wildhorse 7-28** (API # 05-123-12824)

**3 - Unmarked Risers**

*From Previous FIR*

