

Picture 33 shows gas cans and Deasel can  
have Ben moved and stored in fire locker









Picture 40-41 skit has Ben moved to new location and mess has Ben cleaned up with dozer op







Picture 41 Chemical has Ben picked up and  
disposed at the Lincoln co land fill receipt  
fallow





Picture 41 same way






Picture 12 has Ben cleaned up and fluid w  
removed and covered up









Picture 13 this was an exiting couse befo  
location was built





Picture 14 this was here before location w  
built









Picture 20 is the same





Porter pots are good an





Porter pots are secured on location







True statement talked to dozer operator about  
this issue







Picture 7-11 are the same





Picture 12 has Ben cleaned up and fluid w  
removed and covered up

