

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2018

Submitted Date:

08/24/2018

Document Number:

685100503

**FIELD INSPECTION FORM**

Loc ID 313035 Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 51922  
Name of Operator: LYSTER OIL COMPANY INC  
Address: 701 COUNTY ROAD 105  
City: CRAIG State: CO Zip: 81625

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
lyster, brandon	970-326-7533	blysteroil@aol.com	owner operator

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223401	WELL	PR	10/01/2015	OW	081-06765	ELK SPRINGS UNIT 14-8	EI
452632	LAND APPLICATION SITE	AC	10/20/2017		-	ELK SPRINGS UNIT 14-8	EI

**General Comment:**

COGCC staff, Kris Neidel witness the soil sampling on 7/20/2018. Samples were taken as five point composites from the two soil treatment areas. Weather was clear and 80 degs. Treatment area was bermed, soils were reduced to a smaller particle size, with no large clumps of soil. Samples were collected by Lyster Oil staff. The well was shut in at time of inspection.

**Inspected Facilities**

Facility ID: 223401 Type: WELL API Number: 081-06765 Status: PR Insp. Status: EI

Facility ID: 452632 Type: LAND API Number: - Status: AC Insp. Status: EI