

Inspection Photos
Location Name: Cow Skull 11-89-18 #1
API: 05-051-06094



Cow Skull 11-89-18 #1 and #2 well heads.



Tubing on rack in NW corner of location

Inspection Photos
Location Name: Cow Skull 11-89-18 #1
API: 05-051-06094



Cow Skull 11-89-18 tank battery.



Drop out tanks on tank heaters are being blown down onto gravel.

Inspection Photos
Location Name: Cow Skull 11-89-18 #1
API: 05-051-06094



Vertical heated separator and skid mounted compressor.



Stained soil around drain outlet for compressor.