

Final Reclamation Inspection

August 21, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-21105

Inspection Document #: 682403899

Weld County, CO

NWSW Section 21 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HLADKY #12-21A
API: 05-123-21105



Photo 1. Photo taken from the entrance of the well access road, facing North. Well has been plugged and abandoned. Crop growth has not achieved uniform growth as compared to reference areas. Well location will remain in-process. The tank battery is still active and in use by another operator.

Inspection Photos
Location Name: HLADKY #12-21A
API: 05-123-21105



Photo 2. Photo taken from the well location, facing North. Photo illustrates crop growth has not achieved uniform growth as compared to reference areas.

Inspection Photos
Location Name: HLADKY #12-21A
API: 05-123-21105



Photo 3. Photo taken from the well location, facing West. Photo See comments under Photo 2.

