

Inspection Photos

Location Name: Hein-Hart 1 Tank Battery Location ID 451015, Remediation #11686

Inspection Date: 8/24/2018



Photo 1 – Sign and crude oil AST at tank battery.



Photo 2 – Burrow in secondary containment around crude oil tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Hein-Hart 1 Tank Battery Location ID 451015, Remediation #11686

Inspection Date: 8/24/2018



Photo 3 – Containment berm wearing at loadout at crude oil AST.



Photo 4 – Excavation at former produced water vessel.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Hein-Hart 1 Tank Battery Location ID 451015, Remediation #11686

Inspection Date: 8/24/2018



Photo 5 – Excavation and adjacent stockpile at former produced water vessel.



Photo 6 – Wellhead sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Hein-Hart 1 Tank Battery Location ID 451015, Remediation #11686

Inspection Date: 8/24/2018



Photo 7 – Hein-Hart 1 wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources