

Inspection Photos
Location Name: Boies Ranch B-19P Well Pad
Location ID: #335891
Inspection Date: August 20, 2018



Photo #1 – Fenced wellheads, stored equipment, and frac tanks on location, looking east.



Photo #2 – View of bermed frac tanks lining south side of location, looking west.

Inspection Photos
Location Name: Boies Ranch B-19P Well Pad
Location ID: #335891
Inspection Date: August 20, 2018



Photo #3 – Frac tanks are plumbed to support ongoing E&P operations. View of southern tanks, looking west.



Photo #4 – Off-location surface lines leading east from SE corner of location.

Inspection Photos
Location Name: Boies Ranch B-19P Well Pad
Location ID: #335891
Inspection Date: August 20, 2018



Photo #5 – Unlabeled ‘overpack’ container and unused equipment storage inside of north side of tank berm.



Photo #6 – View from northeast corner of tank battery.