

Final Reclamation Inspection

August 21, 2018

Operator: PDC ENERGY INC - 69175

API: 05-123-19814

Inspection Document #: 682403903

Weld County, CO

SESW Section 20 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SUCCO #24-20
API: 05-123-19814



Aerial imagery from 1993 illustrates the tank battery location was not pre-existing.

Inspection Photos
Location Name: SUCCO #24-20
API: 05-123-19814



Aerial imagery from 2017 illustrates the Succo Gas Unit during active operations. Access road and tank battery location have not been reclaimed per Rule 1004.

Inspection Photos
Location Name: SUCCO #24-20
API: 05-123-19814



Photo 1. Photo taken from the well location, facing West. Appears the well location and well access road meet Rule 1004 standards. Unable to find evidence of oil and gas activities and/or disturbances. Well location and access road appear reflective of reference crop areas.



Photo 2. Reference photo taken east of the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: SUCCO #24-20
API: 05-123-19814



Photo 3. Photo taken from the tank battery location, facing South. Operator has failed to perform final reclamation at the tank battery location.