

Final Reclamation Inspection

August 21, 2018

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

API #: 05-123-08029

Inspection Document #: 682403907

Weld County, CO

NWNW Section 29 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: APPEL #2
API #: 05-123-08029



Photo 1. Photo taken from the well location, facing South. Operator has failed to perform all final reclamation activities. There appears to be some gravel and decompaction has not been performed. Last years crop was not able to establish due to the above failed conditions.

Inspection Photos
Location Name: APPEL #2
API #: 05-123-08029



Photo 2. Reference photo taken east of the well location, facing South. Photo illustrates last years crop that has established with no evidence of gravel or bare patches.