

Inspection Photo
Cherokee mountain estates 3-15A
API # 045-15124
Inspection # 689301838



Location Photo #1



Location Photo #2, unmarked anchor

Inspection Photo
Cherokee mountain estates 3-15A
API # 045-15124
Inspection # 689301838



Location Photo #3, unmarked anchor



Location Photo #4, unmarked anchor

Inspection Photo
Cherokee mountain estates 3-15A
API # 045-15124
Inspection # 689301838



Location Photo #5, unmarked anchor



Inspection Photo
Cherokee mountain estates 3-15A
API # 045-15124
Inspection # 689301838



Location Photo #6, leaking fitting at wellhead



Location Photo #7, leaking well ID