

# Interim Reclamation Inspection

August 24, 2018

Operator: ANTELOPE ENERGY COMPANY LLC- #3250

API #: 05-123-32490

Inspection Document #: 682403915

Weld County, CO

SESE Section 16 T9N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: State #9-61-16  
API #: 05-123-32490



**Photo 1.** Photo taken from the tank battery storage area, facing North. Operator has failed to control and manage weeds around equipment.



**Photo 2.** Photo taken from the tank battery storage area, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: State #9-61-16  
API #: 05-123-32490



**Photo 3.** Photo taken north of the tank battery storage area, facing West. See comments under Photo 1.



**Photo 4.** Photo taken north of the tank battery storage area, facing West. See comments under Photo 1.