

Inspection Photos

Loc#335524

Operator: Laramie

Inspection Number: 692400039

Inspection Date: 8/17/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location from entry to East.

August 18,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie RMV Loc#335524



Photo#2:

Disturbed Area occupied by Gravel Pile has not been Reclaimed.

August 18,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie RMV Loc#335524



Photo#3:

Large areas, bare of vegetation remain.

August 18,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie RMV Loc#335524



Photo#4:
Noxious Weed, Russian Knap weed is established on Site

August 18,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie RMV Loc#335524