

Inspection Photos
Operator Name: TEP Rocky Mtn
Location ID: 428956



Spill area behind separators



Spill area behind separators

Inspection Photos
Operator Name: TEP Rocky Mtn
Location ID: 428956



No observation of fluid leaving location



Spill area behind separators

Inspection Photos
Operator Name: TEP Rocky Mtn
Location ID: 428956



Spill area under separators

Inspection Photos
Operator Name: TEP Rocky Mtn
Location ID: 428956



Unmarked riser at wellhead



Unmarked riser at wellhead