

Inspection Photos
Location Name:Ackard 5-2
Location ID:320411



Photo#1 Production Tank and Produced Water Pit



Photo#2 Separator and Automation RTU

Inspection Photos
Location Name:Ackard 5-2
Location ID:320411



Photo#3 Wellhead

