

Inspection Photos

Loc#455049

Operator: Caerus

Inspection Number: 692400059

Inspection Date: 8/22/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to Southwest.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR KO8 Pad Loc#455049



Photo#2:

View of equipment working at what will be base of Fill Slope. Adjacent Location #335682 in background.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR KO8 Pad Loc#455049



Photo#3:
Wattles (or other BMP) not yet installed along Fill side of Access road.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR KO8 Pad Loc#455049



Photo#4:
BMPs being installed around Location Perimeter

August 22, 2018



Photo#5:



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR KO8 Pad Loc#455049