

# *Inspection Photos*

*Loc#334730*

*Operator: Terra*

*Inspection Number: 692400063*

*Inspection Date: 8/28/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Overview of Location and Construction activities to South.

August 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP GV Frac Pad Loc#334730





Photo#2:

Perimeter BMPs have been installed.

August 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP GV Frac Pad Loc#334730





**Photo#3:**  
One BMP failure was noted on Northwest corner of Site.

August 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP GV Frac Pad Loc#334730