

Construction and Stormwater Inspection

August 29, 2018

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - #10633

Location ID: 332117

Inspection Document #: 682403950

Weld County, CO

NWNE Section 22 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Cosslett /22H-B168
Location ID: 332117



Photo 1. Photo taken from the northern perimeter of the location, facing West. Ditch and berm BMP has been installed along the entire perimeter of the location.



Photo 2. Photo taken from the northwest perimeter of the location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Cosslett /22H-B168
Location ID: 332117



Photo 3. Photo taken from the southwestern perimeter of the location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the southern perimeter of the location, facing East. Equipment traffic has damaged a portion of the stormwater BMP. BMPs shall be in proper functioning condition and shall be repaired.

Inspection Photos
Location Name: Cosslett /22H-B168
Location ID: 332117



Photo 5. Photo taken from the southern perimeter of the location, facing North. Photo illustrates topsoil salvage operations are underway.



Photo 6. Photo taken from the northeastern perimeter of the location, facing East. See comments under Photo 1.