

Inspection Photo
Savage RMV 180-29
API # 045-07507
Inspection # 689301843



Location Photo #1




Location Photo #2



Inspection Photo
Savage RMV 180-29
API # 045-07507
Inspection # 689301843



Location Photo #3, non legible battery sign.



Location Photo #4, domestic tap.

Inspection Photo
Savage RMV 180-29
API # 045-07507
Inspection # 689301843



Location Photo #5, weeds on location



Location Photo #6, weeds on location.

Inspection Photo
Savage RMV 180-29
API # 045-07507
Inspection # 689301843



Location Photo #7, debris against fence.



Location Photo #8, open gauge hatch

Inspection Photo
Savage RMV 180-29
API # 045-07507
Inspection # 689301843



Location Photo #9, operator closed gauge hatch.