

Inspection Photo
Savage RMV 101-28
API # 045-07248
Inspection # 689301851



Location Photo #1



Location Photo #2

**Inspection Photo
Savage RMV 101-28
API # 045-07248
Inspection # 689301851**



Location Photo #3, weeds on access drive to wellheads.



Location Photo #4, weeds behind separators.

**Inspection Photo
Savage RMV 101-28
API # 045-07248
Inspection # 689301851**



Location Photo #5, weeds between separators and tank battery.



Location Photo #6, weeds around well head, and non legible sign.

Inspection Photo
Savage RMV 101-28
API # 045-07248
Inspection # 689301851



Location Photo #7, non legible sign



Location Photo #8, Gauge hatch found open.

Inspection Photo
Savage RMV 101-28
API # 045-07248
Inspection # 689301851



Location Photo #9, Photo of gauge hatch that was closed by operator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources