

Inspection Photo
Savage RMF 323-28
API # 045-07915
Inspection # 689301853



Location Photo #1



Location Photo #2

Inspection Photo
Savage RMF 323-28
API # 045-07915
Inspection # 689301853



Location Photo #3, unmarked deadman.



Location Photo #4, weeds on location