

# *Inspection Photos*

*Loc#435460*

*Operator: Terra*

*Inspection Number: 692400065*

*Inspection Date: 8/28/2018*





Photo#1:

Overview of Location From entry to Northwest. Arrow indicates site of area detailed in Photo#3.

August 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP Strait Bottom Ranch Loc#435460



**Photo#2:**

Overview of Location From upper unfinished Access road & top of Cut slope to Southeast. Arrow indicates stormwater flow from road channeling to cut slope; see Photo #3.

August 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP Strait Bottom Ranch Loc#435460



Photo#3:

Stormwater off upper Access road, through road cut out (shown in insert), is being channeled onto Cut slope & developing erosion issue.

August 28, 2018





Photo#4:

View of Perimeter BMPs installed. Arrow indicates where first row of bales have been overwhelmed.

August 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP Strait Bottom Ranch Loc#435460



Photo#5:  
BMPs along Access Road needing maintenance or repair.

August 28, 2018



Photo#6:



Photo#7:

Empty DEF fluid containers were stored in uninstalled culvert/ pipes on Southwest corner of Pad area.

August 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: TEP Strait Bottom Ranch Loc#435460