

Inspection Photos
Location Name:HSR-Van Schaak 13-33
Location ID: 320420



Photo#1 Production Tank and Produced Water Pit




Photo#2 Wellhead

Inspection Photos
Location Name: HSR-Van Schaak 13-33
Location ID: 320420



Thursday, August 30, 2018 10:34:30
 Brighton CO 80603 United States

Photo#3 Separator and Gas Meter



Thursday, August 30, 2018 10:35:44
 Brighton CO 80603 United States

Photo#3 Corrective Action-Gas Meter hasn't been calibrated in over a year. Please Calibrate Meter