

Inspection Photos
Location Name:Box Elder Farms 33-20
Location ID:320462



Photo#1 Production Tank and Produced Water Pit



Photo#2 Wellhead

Inspection Photos
Location Name: Box Elder Farms 33-20
Location ID: 320462



Photo#3 Separator and Gas Meter



Photo#4 Corrective Action/Cinder blocks need to be removed

Inspection Photos
Location Name:Box Elder Farms 33-20
Location ID:320462



Photo#5 Corrective Action/Netting on open tank inadequate. Holes that wildlife can get into.