

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2018

Submitted Date:

08/29/2018

Document Number:

692600162

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 304700 _____ Welsh, Brian _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10489
 Name of Operator: AUGUSTUS ENERGY RESOURCES LLC
 Address: 2016 GRAND AVENUE #A
 City: BILLINGS State: MT Zip: 59102

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273579	WELL	PR	05/11/2005	GW	125-08886	GOODMAN 35-03	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at unit		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Sticker on water tank		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	Meter run is 560' east of wellhead		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:			Date:

Type: Ancillary equipment	# 1	
Comment:	Electric panel	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.088490,-102.379520
Comment:	Fiberglass water tank 50% buried on north side of meter shed				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 273579 Type: WELL API Number: 125-08886 Status: PR Insp. Status: PR

Producing Well

Comment: Producing. Casing production. Meter run is 560' E on west side of CR Z

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: [Access is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT