

Inspection Photos

Loc#422479

Operator: Mesa Energy Partners

Inspection Number: 692400040

Inspection Date: 8/20/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to Northwest. Arrow indicates Sign shown in Photo#2.

August 20,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: MEP Big Duck Creek Loc#422479



Photo#2:

Facilities have Location sign with Laramie Energy identified as Operator.

August 20,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: MEP Big Duck Creek Loc#422479



Photo#3:
Gravel has not been removed.

August 20,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: MEP Big Duck Creek Loc#422479



Photo#4:
Site is Weed infested and soils compacted.

August 20,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: MEP Big Duck Creek Loc#422479



Photo#5:
Site is Weed infested and Soils Compacted.

August 20,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: MEP Big Duck Creek Loc#422479



Photo#6:

Caerus Tank & Facility is adjacent, situated off Southwest corner of subject location..

August 20,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: MEP Big Duck Creek Loc#422479