

Inspection Photos

08/29/2018

Operator: WHITING OIL & GAS CORPORATION -
96155

Location ID: 437030

Inspection Doc. Number: 682503792
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 437030



Photo 1: Photo taken from the west end of the location, facing north. Photos 1-4 provide an overview of the location from north, to west, to south.



Photo 2:

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 437030



Photo 3:



Photo 4:

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 437030



Photo 5: Photo taken from the northwest corner of the location. Facing west. Photo shows interim reclamation in process. Photo also shows stormwater ditch along perimeter.



Photo 6: Photo taken from the north end of the location. Photo shows area where the ditch appears to have filled in over time and erosion degradation is beginning to occur. Advise maintenance to mitigate any additional disturbances.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 437030



Photo 7: Photo taken from the northwest end of the location, facing east.



Photo 8: Photo taken from the northwest end of the location, facing south. Photo shows interim reclamation in process.



Photo 9: Photo taken from the western end of the location, facing southeast. Photo shows areas of the pad that do not appear to be reasonably needed for production. These areas need to be reclaimed.