

**Inspection Photo  
Couey Federal 23-10  
API # 045-12526  
Inspection # 689301865**



**Location Photo #1**



**Location Photo #2, soil movement off of location.**



**Inspection Photo**  
**Couey Federal 23-10**  
**API # 045-12526**  
**Inspection # 689301865**



**Location Photo #3, soil movement off of location.**



**Location Photo #4, soil movement off of location.**



**Inspection Photo**  
**Couey Federal 23-10**  
**API # 045-12526**  
**Inspection # 689301865**



**Location Photo #5, heavy rilling**



**Location Photo #6, soil movement off of location.**



**Inspection Photo**  
**Couey Federal 23-10**  
**API # 045-12526**  
**Inspection # 689301865**



**Location Photo #7, Rilling below rip rap in sediment pond.**



**Location Photo #8, sediment pond**