

Inspection Photo
Savage RWF 12-26
API # 045-16885
Inspection # 689301867



Location Photo #1



Location Photo #2

**Inspection Photo
Savage RWF 12-26
API # 045-16885
Inspection # 689301867**



Location Photo #3, uncontrolled weeds on location.



Location Photo #4, uncontrolled weeds on location.

**Inspection Photo
Savage RWF 12-26
API # 045-16885
Inspection # 689301867**



Location Photo #5, uncontrolled weeds on location.



Location Photo #6, uncontrolled weeds on location.

**Inspection Photo
Savage RWF 12-26
API # 045-16885
Inspection # 689301867**



Location Photo #7, uncontrolled weeds on access road.



Location Photo #8, uncontrolled weeds on access road.